

Republic of the Philippines

Partido Development Administration

Created Under R.A. 7820 Caraycayon, Tigaon, Camarines Sur

PRICE QUOTATION

Sir/Gentlen

Please quote your price/s of the following articles which this office desire to purchase for use in RESTORATION OF DAMAGED CONCRETE PAVEMENT & FIRE HYDRANT POST IN TINAMBAC CAM. SUR

Item#	Particulars	Qty.	Unit	Unit Cost	Total Cost
	Supply of labor & materials for the Restoration of				
	damaged concrete pavement & Fire Hydrant post from				
	Poblacion, Sta. Cruz to Brgy. Bagacay in Tinambac,				7
	Cam. Sur				
1	Materials :				
	1. Cement (Portland)				•
	2. Sand				
	3. Gravel (aggregate)				
	4. G.I. pipe, 3" dia., sched. 40				
	5. Reflectorized paint (orange)				
	6. Reflectorized paint (white)				
	7. Paint brush #2 & #4				
	8. Paint thinner				н
2	Equipment/FOL				
	1. Plate compactor	•			
	2. Concrete breaker				
	3. Concrete mixer (1-bagger)				
	4. FOL (Fuel, oil & lubricant)				
3	Labor:				
	Restoration of concrete pavement				
	concrete breaking/demolition				
	Surface preparation/compaction				
	3. concreting of pavement				
	2. Restoration of Fire Hydrant post				
	Repair/replacement of post				
	2. Re-painting of fire hydrant & post				

Dealer : FIN: VAT#	N-VAT#	
Address :	and the second s	
Contact Person:		
Canvasser		
Sir/Madam:		

I have the honor to offer my prices for each of the above articles as indicated after each item hereon.

Very truly yours,