

Republic of the Philippines PARTIDO DEVELOPMENT ADMINISTRATION

Created Under R.A. 7820 Tigaon, Camarines Sur

. 20		
	20	

PRICE QUOTATION

	lam: quote your prices of the following articles which this o aintenance of damaged main distribution lines.	ffice desi	re to purc	chase for us	e in <u><i>repair</i></u>
ITEM #	PARTICULARS	QTY.	UNIT	UNIT COST	TOTAL COST
1 2 3 4 5	400mm (16") CI Sleeve Type Couplings 355mm (14") CI Sleeve Type Couplings 315mm (12") CI Sleeve Type Couplings 355mm (14") CI Saddle Clamp x ¾" 315mm (12") CI Saddle Clamp x ¾"	4 4 20 10 10	Pcs Pcs Pcs Pcs Pcs		
Contact Canvas Sir/Mac	AT#: s: one No.: Person: ser:			fter each ite	
				v Ci y ti	ary yours

PDA-F-PROC/PQ-01 Rev. No. 0 September 1, 2015